

**PROJECT NO. 36157**

**COMPLIANCE REPORT OF  
ONCOR ELECTRIC DELIVERY  
COMPANY LLC PURSUANT TO  
THE COMMISSION'S ORDER  
ISSUED IN DOCKET NO. 35718**

§  
§  
§  
§  
§

**BEFORE THE  
PUBLIC UTILITY COMMISSION  
OF TEXAS**

**COMPLIANCE REPORT OF  
ONCOR ELECTRIC DELIVERY COMPANY LLC FOR SEPTEMBER 2010  
PURSUANT TO THE COMMISSION'S ORDER ISSUED IN DOCKET NO. 35718**

TO THE HONORABLE PUBLIC UTILITY COMMISSION OF TEXAS:

COMES NOW Oncor Electric Delivery Company LLC (“Oncor”) and files this compliance report (this “Compliance Report”) as required by the Public Utility Commission of Texas (the “Commission”) in Docket No. 35718<sup>1</sup> and respectfully shows the following:

**I. DESIGNATED REPRESENTATIVES**

For purposes of this filing, Oncor’s designated representatives are as follows:

Jo Ann Biggs  
Vinson & Elkins LLP  
Trammel Crow Center  
2001 Ross Avenue, Suite 3700  
Dallas, Texas 75201-2975  
(214) 220-7700 Office  
(214) 220-7716 Fax  
Email: jbiggs@velaw.com

and

---

<sup>1</sup> *Oncor Electric Delivery Company LLC's Request for Approval of AMS Deployment Plan and Request for AMS Surcharge*, Docket No. 35718.

Ronnie Puckett  
Senior Regulatory Project Manager  
Oncor Electric Delivery Company LLC  
1601 Bryan Street, Suite 23-120C  
Dallas, Texas 75201  
214.486.2214 Office  
214.486.3221 Fax  
Email: rpuckett@oncor.com

## **II. BACKGROUND AND REASON FOR FILING**

On May 28, 2008, Oncor filed a request for approval of AMS deployment plan and request for AMS surcharge. On July 24, 2008, Oncor filed a supplemental request for approval of AMS deployment plan and AMS surcharge. In the supplemental request, Oncor made minor changes to its AMS Surcharge Model that resulted in a lower net estimated cost of advanced metering system facilities, a lower total levelized revenue requirement, and a lower proposed AMS surcharge. On August 11, 2008, a Stipulation was signed by most of the parties to the docket. (the “Stipulation”). The remaining parties either expressed no interest in participating in settlement discussions or were in agreement with the terms of the Stipulation.

In the Stipulation, Oncor agreed to file a monthly status report covering various issues and a quarterly report covering customer education activities with the Commission. Oncor subsequently decided to report on the customer education activities monthly. These reports are in addition to the reporting requirements contained in Commission Substantive Rule § 25.130 (the “Advanced Metering Rule”).

On August 29, 2008, the Commission issued its Order approving the Stipulation, including the reporting requirements, and approving Oncor’s request for approval of AMS deployment plan and AMS surcharge, consistent with the agreements made in the Stipulation.

This Compliance Report covers the period of September 2010 and meets the requirements of the Stipulation and the Advanced Metering Rule.

### III. REPORT

- (1) Number of advanced meters installed, listed by ESIID, with geographic identification.

**Report:** As of September 30, 2010, 1,343,458 advanced meters have been installed. The ESIID electronic documents listing installed advanced meters will be provided to REPs through the FTP site at <ftp.oncor.com> in the folder labeled AMS Meters. The files list all meters installed by ESIID and indicate whether the meter has been provisioned. This report is updated on a weekly basis.

- (2) By January 31, 2009, the ESIIDs with advanced meters and whether that meter is RF or PLC (additional information required by Project No. 34610).

**Report:** See (1) as described above.

- (3) Significant delays or deviation from the AMS deployment plan and reasons for delay or deviation.

**Report:** As of September 30, 2010, there have been no significant delays or deviations from the AMS Deployment Plan. Oncor plans to generally cover the same geographical area specified in its AMS Deployment Plan for 2010. Oncor now expects that the actual number of meters installed at year end will be less than the number estimated for 2010 in the approved AMS Deployment Plan because the originally estimated customer growth rate has not been realized.

- (4) A description of significant problems experienced with the AMS, with an explanation of how the problems are being addressed.

**Report:** In September 2010, there were no significant problems experienced with the Oncor AMS.

- (5) Number of advanced meters that have been replaced as a result of problems with the AMS.

**Report:** As of September 30, 2010, no advanced meters have been replaced as a result of problems with the AMS. Since AMS deployment began in 2008, there have been a total of 770 advanced meters replaced due to a meter-related failure. See the response to item (6) below and Annex A to this Report.

**On July 30, 2010, Oncor committed to replace on an expedited basis any Rev-D meter that exhibits Event Code 2118. During September 2010, 22 meters (6 Rev-D meters and 16 non-Rev-D meters) exhibited Event Code 2118. Those meters have been replaced.**

- (6) Records of advanced meter failure and repair rates and costs incurred as a result of those failures and repairs, net of warranty payments.

**Report:** Annex A reflects the reports of failures of advanced meters. The advanced meter failure rates are 0.06%, and the repair rates are 100%. As of September 30, 2010, an estimated \$24,493 in additional costs have been incurred as a result of advanced meter failure. These costs are net of warranty payments and are essentially the handling costs for Oncor to return the meters back to the factory. Please note that Landis+Gyr has agreed to reimburse Oncor for all costs incurred by Oncor in the replacement of Rev-D meters, including any related shipping costs.

- (7) Status of deployment of features identified in the AMS deployment plan and any changes in deployment of these features.

**Report:** As of September 30, 2010, there have been no changes in deployment of features identified in the AMS deployment plan.

- (8) Status of the availability of poly-phase, class 200 (200 amp rating) advanced meters with remotely controlled disconnect/reconnect devices required by Substantive Rule §25.130(g)(1).

**Report:** As of September 30, 2010, poly-phase, class 200 advanced meters with remotely controlled disconnect/reconnect devices are not available for the Oncor AMS.

- (9) Status of the availability of poly-phase, instrument rated advanced meters with HAN communication functionality required by Substantive Rule § 25.130(g)(1).

**Report:** As of September 30, 2010, Oncor has approved for use three poly-phase, instrument rated advanced meters (forms 6, 9, and 45) with HAN communication functionality.

- (10) Status of compliance with ANSI C12.22.

**Report:** Based on the approved version of ANSI C12.22, the Oncor AMS will be compliant.

- (11) Status of achieving the ability to support HAN functionality between one device in the home by March 31, 2009.

**Report:** On March 31, 2009, Oncor achieved the ability to support HAN functionality between provisioned advanced meters and one device in the home.

- (12) Status of achieving the ability to support HAN functionality determined in Project No. 34610.

**Report:** As of January 31, 2010, Oncor's advanced metering system supports provisioning/deprovisioning up to five in-home devices, transmitting pricing signals, direct load control or thermostat adjustment signals, and text messaging using ZigBee Smart Energy Profile 1.0. Messages and control signals can be sent point-to-point or broadcast. As of September 30, 2010, nine in-home devices from seven vendors have been validated to operate with the Oncor AMS.

- (13) Status of achieving the ability to support Time of Use ("TOU") functionality by May 1, 2009.

**Report:** On May 1, 2009, Oncor achieved the ability to support TOU functionality for provisioned advanced meters.

- (14) Status of achieving the ability to support prepaid service by June 1, 2009.

**Report:** On June 1, 2009, Oncor achieved the ability to support prepaid service for provisioned advanced meters.

- (15) Status of achieving the ability to support settlement at ERCOT no later than July 1, 2009.

**Report:** On June 30, 2009, Oncor achieved the ability to support settlement at ERCOT for provisioned advanced meters. Oncor began providing 15-minute interval data to ERCOT for settlement purposes on December 6, 2009.

- (16) Status of web portal deployment.

**Report:** On March 23, 2010, the Smart Meter Texas ("SMT") Portal User Interface was launched. The SMT Portal development team in conjunction with the AMIT working group implemented a new change management methodology to improve control and communication. PUC AMIT workshops for SMT Portal Release 2 started in April 2010 to define added market requirements such as M2, M3, and HAN. Release 2 of the SMT Portal was placed in service on August 8, 2010.

- (17) Status of web portal security audit.

**Report:** During the month of January 2010, CenterPoint and Oncor engaged an independent security audit firm to review the production-ready Smart Meter

**Texas physical hosting site and application. Several security tests were performed prior to placing the Smart Meter Texas solution into production.**

- (18) Status of implementation of the low-income monitor program.

**Report: On June 15, 2010, the Joint TDUs (AEP Texas, CenterPoint, and Oncor), Commission Staff, the Office of Public Utility Counsel, and the Texas Ratepayers' Organization to Save Energy (collectively, the "RFP Review Team") decided to postpone making a decision on a potential vendor(s) as solicited in the Request For Proposals dated May 3, 2010 for a period of three to six months.**

**CenterPoint and Oncor each received permission from the Commission to provide in-home monitors to up to 500 end-use customers. The RFP Review Team decided to gain insight from these deployments prior to proceeding with any decisions related to in-home monitors for the low-income programs.**

**Additionally, the Joint TDUs, in collaboration with the ZigBee Alliance, have been hosting ZigFesTx events. These events, open to ZigBee Alliance members, are a series of Texas-based engineering working sessions where device manufacturers, representatives from the ZigBee Alliance, and the Joint TDUs gather to test, refine, and prove out the functional requirements and performance parameters of the various ZigBee HAN devices, and to test devices for interoperability among the Joint TDUs' advanced metering systems. The RFP Review Team encouraged the RFP respondents to have their technical personnel participate in these events, because the RFP Review Team will also use feedback from ZigFesTx in selecting potential vendors.**

- (19) Status of efforts to pursue funding under the Energy Independence & Security Act.

**Report: In July 2009, Oncor filed an application for a Smart Grid Investment Grant for its AMS in response to the U.S. Department of Energy's Funding Opportunity Announcement DE-FOA-000058. That Solicitation was conducted pursuant to § 1306 of the Energy Independence and Security Act of 2007 and the American Recovery and Reinvestment Act of 2009. In October 2009, Oncor was informed by the Department of Energy that it had not been selected to receive an award.**

- (20) Status of customer education efforts.

**Report: During September 2010, the Smart Texas education campaign hosted eight Mobile Experience Center events, four static events, and two table top events. Total visitors for the month were 3,105. There were 73,079 pre-deployment door hangers distributed in the Arlington and Waxahachie Metering District.**

**An estimated 1,201,330 consumers were reached through local and national media coverage. Public advertising coverage had 8,020,572 impressions and includes South Fort Worth, Waco, Waxahachie, and Wichita Falls Metering Districts through movie theater, billboard, online, and newspaper ads. Social media sites, including Twitter and Facebook, continue to be used to inform the public of events, general information, and contests.**

**In September 2010, the AMS call center received 1,243 calls. Of those, 450 were answered in IVR, five calls were abandoned, 710 were answered by English agents, and 78 were answered by Spanish agents. Eighty-four percent of these calls were answered in 20 seconds or less. Call volume increased 15 percent compared to August. The majority of the calls were general inquiries regarding when will my meter be installed, how do I read the meter, what are the benefits of the new meter, and questions about the Smart Meter Texas portal.**

Respectfully submitted,

Vinson & Elkins LLP

By:   
Jo Ann Biggs  
State Bar No. 02312400

Trammel Crow Center  
2001 Ross Avenue, Suite 3700  
Dallas, Texas 75201-2975  
(214) 220-7700 Office  
(214) 220-7716 Fax

ATTORNEYS FOR ONCOR ELECTRIC DELIVERY  
COMPANY LLC

**Annex A  
Oncor Advanced Meter Failures**

<b>AMS Meter Failures for January 2009 Through September 2010</b>							
<b>Date Reported</b>	<b>Com Type</b>	<b>Serial Number</b>	<b>ProblemCategory</b>	<b>Meter Shop Cost</b>	<b>Loaded Cost</b>	<b>Field Adder</b>	<b>Cost Per Unit</b>
01/22/2009	RF-Mesh	101040465	Test Switch Broken or Inoperable	\$7.50	\$12.08	\$10.00	\$22.08
01/22/2009	RF-Mesh	101067626	Blank/Partial Display	\$7.50	\$12.08	\$10.00	\$22.08
01/22/2009	RF-Mesh	101042826	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
01/22/2009	RF-Mesh	101044341	Test Switch Broken or Inoperable	\$7.50	\$12.08	\$10.00	\$22.08
01/22/2009	RF-Mesh	101044332	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
01/22/2009	RF-Mesh	101049261	Blank/Partial Display	\$7.50	\$12.08	\$10.00	\$22.08
01/22/2009	RF-Mesh	101057236	Blank/Partial Display	\$7.50	\$12.08	\$10.00	\$22.08
01/26/2009	RF-Mesh	101043754	Blank/Partial Display	\$7.50	\$12.08	\$10.00	\$22.08
01/26/2009	RF-Mesh	101058889	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
01/27/2009	RF-Mesh	101039245	Blank/Partial Display	\$7.50	\$12.08	\$10.00	\$22.08
01/27/2009	RF-Mesh	101039005	Blank/Partial Display	\$7.50	\$12.08	\$10.00	\$22.08
01/27/2009	RF-Mesh	101060749	Error Codes	\$15.01	\$24.16	\$10.00	\$34.16
01/27/2009	RF-Mesh	101055810	Blank/Partial Display	\$7.50	\$12.08	\$10.00	\$22.08
01/27/2009	RF-Mesh	101039055	Not Communicating	\$22.51	\$36.25	\$10.00	\$46.25
02/20/2009	RF-Mesh	101044663	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
02/20/2009	RF-Mesh	101055252	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
02/20/2009	RF-Mesh	101043725	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
02/20/2009	RF-Mesh	101064450	Test Switch Broken or Inoperable	\$15.01	\$24.16	\$10.00	\$34.16
02/24/2009	RF-Mesh	101096750	Erratic Register Reading	\$7.50	\$12.08	\$10.00	\$22.08
02/24/2009	RF-Mesh	101041011	Blank/Partial Display	\$7.50	\$12.08	\$10.00	\$22.08
03/03/2009	RF-Mesh	101052316	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
03/04/2009	RF-Mesh	101101063	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
03/04/2009	RF-Mesh	101101636	Blank/Partial Display	\$7.50	\$12.08	\$10.00	\$22.08
03/09/2009	RF-Mesh	101043805	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
03/09/2009	RF-Mesh	101093599	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
03/09/2009	RF-Mesh	101039273	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
03/09/2009	RF-Mesh	101066799	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
03/09/2009	RF-Mesh	101040258	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
03/09/2009	RF-Mesh	101058616	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
03/09/2009	RF-Mesh	101048308	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
03/09/2009	RF-Mesh	101043662	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
03/09/2009	RF-Mesh	101040796	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
03/09/2009	RF-Mesh	101039475	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
03/10/2009	RF-Mesh	101052869	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
03/12/2009	RF-Mesh	101040426	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
03/12/2009	RF-Mesh	101046255	Stopped Meter/No Rotation Annunciator	\$15.01	\$24.16	\$10.00	\$34.16
03/12/2009	RF-Mesh	101075620	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
03/12/2009	RF-Mesh	101059175	Blank/Partial Display	\$7.50	\$12.08	\$10.00	\$22.08
03/17/2009	RF-Mesh	101040403	Erratic Register Reading	\$7.50	\$12.08	\$10.00	\$22.08
03/17/2009	RF-Mesh	101068072	Blank/Partial Display	\$7.50	\$12.08	\$10.00	\$22.08
03/20/2009	RF-Mesh	101257634	Component Failure	\$7.50	\$12.08	\$10.00	\$22.08
03/20/2009	RF-Mesh	101253658	Error Codes	\$15.01	\$24.16	\$10.00	\$34.16
03/20/2009	RF-Mesh	101259692	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
03/20/2009	RF-Mesh	101253077	Component Failure	\$7.50	\$12.08	\$10.00	\$22.08
03/23/2009	RF-Mesh	101240226	Blank/Partial Display	\$7.50	\$12.08	\$10.00	\$22.08
03/24/2009	RF-Mesh	101095044	Erratic Register Reading	\$7.50	\$12.08	\$10.00	\$22.08
03/24/2009	RF-Mesh	101047622	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
03/26/2009	RF-Mesh	101254926	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
03/26/2009	RF-Mesh	101256138	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
03/26/2009	RF-Mesh	101041405	Blank/Partial Display	\$7.50	\$12.08	\$10.00	\$22.08
03/27/2009	RF-Mesh	101089487	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
04/01/2009	RF-Mesh	101255825	Component Failure	\$7.50	\$12.08	\$10.00	\$22.08
04/01/2009	RF-Mesh	101252764	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
04/01/2009	RF-Mesh	101086780	Component Failure	\$7.50	\$12.08	\$10.00	\$22.08
04/03/2009	RF-Mesh	101269362	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
04/03/2009	RF-Mesh	101059147	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16

**Annex A  
Oncor Advanced Meter Failures**

<b>AMS Meter Failures for January 2009 Through September 2010</b>							
<b>Date Reported</b>	<b>Com Type</b>	<b>Serial Number</b>	<b>ProblemCategory</b>	<b>Meter Shop Cost</b>	<b>Loaded Cost</b>	<b>Field Adder</b>	<b>Cost Per Unit</b>
04/03/2009	RF-Mesh	101236562	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
04/06/2009	RF-Mesh	101265749	Blank/Partial Display	\$7.50	\$12.08	\$10.00	\$22.08
04/07/2009	RF-Mesh	101110449	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
04/07/2009	RF-Mesh	101263458	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
04/07/2009	RF-Mesh	101056707	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
04/07/2009	RF-Mesh	101250701	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
04/08/2009	RF-Mesh	101104940	Test Switch Broken or Inoperable	\$7.50	\$12.08	\$10.00	\$22.08
04/08/2009	RF-Mesh	101468359	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
04/13/2009	RF-Mesh	101236654	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
04/13/2009	RF-Mesh	101062983	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
04/13/2009	RF-Mesh	101098475	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
04/13/2009	RF-Mesh	101058738	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
04/14/2009	RF-Mesh	101246156	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
04/23/2009	RF-Mesh	101101022	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
04/24/2009	RF-Mesh	101089589	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
04/24/2009	RF-Mesh	101089677	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
04/29/2009	RF-Mesh	101100923	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
04/29/2009	RF-Mesh	101077962	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
04/29/2009	RF-Mesh	101058228	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
04/30/2009	RF-Mesh	101095706	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
04/30/2009	RF-Mesh	101236948	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
05/05/2009	RF-Mesh	101090026	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
05/06/2009	RF-Mesh	101047058	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
05/07/2009	RF-Mesh	101057321	Blank/Partial Display	\$7.50	\$12.08	\$10.00	\$22.08
05/14/2009	RF-Mesh	101472397	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
05/15/2009	RF-Mesh	101468037	Blank/Partial Display	\$7.50	\$12.08	\$10.00	\$22.08
05/15/2009	RF-Mesh	101985659	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
05/15/2009	RF-Mesh	101107059	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
05/28/2009	RF-Mesh	101077835	Blank/Partial Display	\$7.50	\$12.08	\$10.00	\$22.08
05/28/2009	RF-Mesh	101058680	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
05/28/2009	RF-Mesh	101228199	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
06/03/2009	RF-Mesh	101111565	ETM Unable To Handshake With Meter	\$15.01	\$24.16	\$10.00	\$34.16
06/03/2009	RF-Mesh	101047740	ETM Unable To Handshake With Meter	\$15.01	\$24.16	\$10.00	\$34.16
07/02/2009	RF-Mesh	101983340	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
07/02/2009	RF-Mesh	101484745	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
07/07/2009	RF-Mesh	101988675	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
07/07/2009	RF-Mesh	101985694	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
07/09/2009	RF-Mesh	101265584	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
07/09/2009	RF-Mesh	101228302	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
07/14/2009	RF-Mesh	101272236	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
07/20/2009	RF-Mesh	102467380	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
07/23/2009	RF-Mesh	101049902	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
07/27/2009	RF-Mesh	102423792	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
07/27/2009	RF-Mesh	101248473	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
07/28/2009	RF-Mesh	102439711	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
07/29/2009	RF-Mesh	101291728	ETM Unable To Handshake With Meter	\$15.01	\$24.16	\$10.00	\$34.16
07/29/2009	RF-Mesh	101280051	Zigbee Not Communicating	\$7.50	\$12.08	\$10.00	\$22.08
07/30/2009	RF-Mesh	101040029	Blank/Partial Display	\$7.50	\$12.08	\$10.00	\$22.08
07/30/2009	RF-Mesh	101241641	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/03/2009	RF-Mesh	101472140	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
08/03/2009	RF-Mesh	101087728	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
08/04/2009	RF-Mesh	101249364	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
08/04/2009	RF-Mesh	101470933	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
08/04/2009	RF-Mesh	101251602	ETM Unable To Handshake With Meter	\$15.01	\$24.16	\$10.00	\$34.16
08/04/2009	RF-Mesh	101087913	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
08/04/2009	RF-Mesh	101476495	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25

**Annex A  
Oncor Advanced Meter Failures**

<b>AMS Meter Failures for January 2009 Through September 2010</b>							
<b>Date Reported</b>	<b>Com Type</b>	<b>Serial Number</b>	<b>ProblemCategory</b>	<b>Meter Shop Cost</b>	<b>Loaded Cost</b>	<b>Field Adder</b>	<b>Cost Per Unit</b>
08/04/2009	RF-Mesh	102442254	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/05/2009	RF-Mesh	101232915	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
08/05/2009	RF-Mesh	101041722	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
08/05/2009	RF-Mesh	101067401	ETM Unable To Handshake With Meter	\$15.01	\$24.16	\$10.00	\$34.16
08/05/2009	RF-Mesh	101276055	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/05/2009	RF-Mesh	101040973	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/05/2009	RF-Mesh	101053536	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/05/2009	RF-Mesh	101055600	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/05/2009	RF-Mesh	101269641	ETM Unable To Handshake With Meter	\$15.01	\$24.16	\$10.00	\$34.16
08/06/2009	RF-Mesh	101251470	ETM Unable To Handshake With Meter	\$15.01	\$24.16	\$10.00	\$34.16
08/06/2009	RF-Mesh	101093130	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/06/2009	RF-Mesh	101073730	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/06/2009	RF-Mesh	101076987	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/06/2009	RF-Mesh	101076943	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/06/2009	RF-Mesh	101230231	ETM Unable To Handshake With Meter	\$15.01	\$24.16	\$10.00	\$34.16
08/06/2009	RF-Mesh	101233539	ETM Unable To Handshake With Meter	\$15.01	\$24.16	\$10.00	\$34.16
08/07/2009	RF-Mesh	102466335	ETM Unable To Handshake With Meter	\$15.01	\$24.16	\$10.00	\$34.16
08/12/2009	RF-Mesh	102453587	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
08/17/2009	RF-Mesh	102594343	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/17/2009	RF-Mesh	101086928	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
08/17/2009	RF-Mesh	102429401	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/18/2009	RF-Mesh	102465451	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/19/2009	RF-Mesh	102607062	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/19/2009	RF-Mesh	102609263	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/19/2009	RF-Mesh	101999259	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/19/2009	RF-Mesh	101988434	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/20/2009	RF-Mesh	101305520	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
08/20/2009	RF-Mesh	101253972	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
08/20/2009	RF-Mesh	101475400	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/20/2009	RF-Mesh	102427404	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/20/2009	RF-Mesh	101108745	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/21/2009	RF-Mesh	101101857	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/25/2009	RF-Mesh	101241318	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/26/2009	RF-Mesh	102450440	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/26/2009	RF-Mesh	101045719	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/27/2009	RF-Mesh	101294861	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/27/2009	RF-Mesh	101083409	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/27/2009	RF-Mesh	101247196	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/27/2009	RF-Mesh	101291014	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/27/2009	RF-Mesh	101476425	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
08/27/2009	RF-Mesh	102457278	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/27/2009	RF-Mesh	101081088	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
08/28/2009	RF-Mesh	101482523	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
09/03/2009	RF-Mesh	101994253	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
09/03/2009	RF-Mesh	103229938	Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
09/03/2009	RF-Mesh	101229928	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/03/2009	RF-Mesh	101259130	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
09/03/2009	RF-Mesh	101089373	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/08/2009	RF-Mesh	103629190	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/10/2009	RF-Mesh	101252427	Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
09/10/2009	RF-Mesh	102003352	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
09/10/2009	RF-Mesh	102438040	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
09/10/2009	RF-Mesh	101079518	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
09/11/2009	RF-Mesh	101060000	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
09/11/2009	RF-Mesh	101052316	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/11/2009	RF-Mesh	101040937	Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16

**Annex A  
Oncor Advanced Meter Failures**

AMS Meter Failures for January 2009 Through September 2010							
Date Reported	Com Type	Serial Number	ProblemCategory	Meter Shop Cost	Loaded Cost	Field Adder	Cost Per Unit
09/11/2009	RF-Mesh	101279963	Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
09/11/2009	RF-Mesh	101304816	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/14/2009	RF-Mesh	101087939	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
09/14/2009	RF-Mesh	101087968	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
09/14/2009	RF-Mesh	101085394	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
09/14/2009	RF-Mesh	101086460	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
09/14/2009	RF-Mesh	101087800	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
09/14/2009	RF-Mesh	101087747	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
09/14/2009	RF-Mesh	101087426	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
09/14/2009	RF-Mesh	101087758	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
09/14/2009	RF-Mesh	101087427	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
09/14/2009	RF-Mesh	101086907	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
09/14/2009	RF-Mesh	101087344	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
09/14/2009	RF-Mesh	101087459	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
09/14/2009	RF-Mesh	101085372	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
09/14/2009	RF-Mesh	101087453	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
09/14/2009	RF-Mesh	101086152	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
09/14/2009	RF-Mesh	102438221	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/14/2009	RF-Mesh	102425379	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/14/2009	RF-Mesh	101984254	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/15/2009	RF-Mesh	103620336	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/15/2009	RF-Mesh	103629362	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/15/2009	RF-Mesh	102614641	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/15/2009	RF-Mesh	102469717	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/15/2009	RF-Mesh	101053156	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
09/15/2009	RF-Mesh	101052594	Error Codes	\$15.01	\$24.16	\$10.00	\$34.16
09/15/2009	RF-Mesh	101301058	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/15/2009	RF-Mesh	103623743	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/16/2009	RF-Mesh	102614841	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/16/2009	RF-Mesh	101279573	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/16/2009	RF-Mesh	101045994	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
09/18/2009	RF-Mesh	102464338	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/18/2009	RF-Mesh	101097576	Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
09/18/2009	RF-Mesh	101084067	ETM Unable To Handshake With Meter	\$15.01	\$24.16	\$10.00	\$34.16
09/22/2009	RF-Mesh	101992369	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/23/2009	RF-Mesh	101102951	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/23/2009	RF-Mesh	101105945	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/23/2009	RF-Mesh	101104128	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/23/2009	RF-Mesh	101994529	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
09/23/2009	RF-Mesh	101060808	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/23/2009	RF-Mesh	101486739	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/23/2009	RF-Mesh	101087293	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/24/2009	RF-Mesh	101243314	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/25/2009	RF-Mesh	102444367	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/25/2009	RF-Mesh	102457964	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/26/2009	RF-Mesh	101285283	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/26/2009	RF-Mesh	102428786	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/26/2009	RF-Mesh	101109046	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/28/2009	RF-Mesh	102440238	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/28/2009	RF-Mesh	102461737	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/29/2009	RF-Mesh	102007745	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/29/2009	RF-Mesh	101483042	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
09/30/2009	RF-Mesh	101089807	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/01/2009	RF-Mesh	101102278	C/U Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/01/2009	RF-Mesh	102436148	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/01/2009	RF-Mesh	102613283	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16

**Annex A  
Oncor Advanced Meter Failures**

<b>AMS Meter Failures for January 2009 Through September 2010</b>							
<b>Date Reported</b>	<b>Com Type</b>	<b>Serial Number</b>	<b>ProblemCategory</b>	<b>Meter Shop Cost</b>	<b>Loaded Cost</b>	<b>Field Adder</b>	<b>Cost Per Unit</b>
10/02/2009	RF-Mesh	101057052	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
10/06/2009	RF-Mesh	102617549	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/06/2009	RF-Mesh	101479291	Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
10/06/2009	RF-Mesh	102616596	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/07/2009	RF-Mesh	101094864	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/07/2009	RF-Mesh	102616042	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/08/2009	RF-Mesh	101105952	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/08/2009	RF-Mesh	102008287	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/08/2009	RF-Mesh	103632044	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/09/2009	RF-Mesh	101051751	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/09/2009	RF-Mesh	102445556	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/09/2009	RF-Mesh	101987982	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/09/2009	RF-Mesh	101040177	ETM Unable To Handshake With Meter	\$15.01	\$24.16	\$10.00	\$34.16
10/09/2009	RF-Mesh	102611087	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/12/2009	RF-Mesh	101094579	Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
10/12/2009	RF-Mesh	101260115	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/12/2009	RF-Mesh	101094909	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
10/12/2009	RF-Mesh	101061279	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/12/2009	RF-Mesh	101089201	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
10/12/2009	RF-Mesh	101089904	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
10/12/2009	RF-Mesh	101040427	Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
10/12/2009	RF-Mesh	101093358	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
10/12/2009	RF-Mesh	101231302	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
10/12/2009	RF-Mesh	101060965	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/13/2009	RF-Mesh	101080666	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/13/2009	RF-Mesh	101269903	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/13/2009	RF-Mesh	103649371	Stopped Meter/No Rotation Annunciator	\$15.01	\$24.16	\$10.00	\$34.16
10/13/2009	RF-Mesh	101279256	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
10/13/2009	RF-Mesh	101044911	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/13/2009	RF-Mesh	101995907	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/13/2009	RF-Mesh	102605379	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
10/14/2009	RF-Mesh	102591579	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/15/2009	RF-Mesh	101041512	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/16/2009	RF-Mesh	101247138	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
10/16/2009	RF-Mesh	102600023	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/21/2009	RF-Mesh	101295061	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
10/21/2009	RF-Mesh	101076202	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/21/2009	RF-Mesh	101999096	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/21/2009	RF-Mesh	101276672	Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
10/21/2009	RF-Mesh	101051846	Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
10/21/2009	RF-Mesh	101235811	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
10/21/2009	RF-Mesh	101043440	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
10/21/2009	RF-Mesh	101264905	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
10/21/2009	RF-Mesh	101468253	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/21/2009	RF-Mesh	101090822	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/21/2009	RF-Mesh	101096688	Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
10/21/2009	RF-Mesh	101229948	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
10/22/2009	RF-Mesh	101049052	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/22/2009	RF-Mesh	102453574	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
10/22/2009	RF-Mesh	102604771	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
10/22/2009	RF-Mesh	102605530	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/26/2009	RF-Mesh	102602229	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/26/2009	RF-Mesh	102454735	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
10/28/2009	RF-Mesh	101083047	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
10/29/2009	RF-Mesh	101087282	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
11/03/2009	RF-Mesh	101086818	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16

**Annex A  
Oncor Advanced Meter Failures**

<b>AMS Meter Failures for January 2009 Through September 2010</b>							
<b>Date Reported</b>	<b>Com Type</b>	<b>Serial Number</b>	<b>ProblemCategory</b>	<b>Meter Shop Cost</b>	<b>Loaded Cost</b>	<b>Field Adder</b>	<b>Cost Per Unit</b>
11/03/2009	RF-Mesh	102456438	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
11/04/2009	RF-Mesh	103633340	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
11/05/2009	RF-Mesh	101304182	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
11/05/2009	RF-Mesh	101230091	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
11/09/2009	RF-Mesh	102598170	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
11/12/2009	RF-Mesh	103273804	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
11/18/2009	RF-Mesh	101238853	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
11/18/2009	RF-Mesh	101483011	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
11/18/2009	RF-Mesh	102431903	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
11/19/2009	RF-Mesh	102610812	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
11/19/2009	RF-Mesh	102443061	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
11/19/2009	RF-Mesh	103644571	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
12/18/2009	RF-Mesh	103518488	Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
12/22/2009	RF-Mesh	103454001	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
12/28/2009	RF-Mesh	103248554	Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
12/29/2009	RF-Mesh	103615344	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
12/29/2009	RF-Mesh	102613573	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
12/31/2009	RF-Mesh	101087837	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
01/05/2010	RF-Mesh	101105340	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
01/05/2010	RF-Mesh	101085413	Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
01/05/2010	RF-Mesh	102460014	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
01/06/2010	RF-Mesh	102617628	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
01/07/2010	RF-Mesh	101302979	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
01/14/2010	RF-Mesh	103637852	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
01/14/2010	RF-Mesh	102615442	Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
01/21/2010	RF-Mesh	102594489	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
01/21/2010	RF-Mesh	101078436	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
01/21/2010	RF-Mesh	101234284	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
01/26/2010	RF-Mesh	103622796	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
01/26/2010	RF-Mesh	101069203	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
01/26/2010	RF-Mesh	102475259	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
01/29/2010	RF-Mesh	102442479	Unable To Test	\$15.01	\$24.16	\$10.00	\$34.16
01/29/2010	RF-Mesh	101040056	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
02/02/2010	RF-Mesh	103502812	Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
02/03/2010	RF-Mesh	103234029	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
02/09/2010	RF-Mesh	101040081	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
02/11/2010	RF-Mesh	103417348	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
02/12/2010	RF-Mesh	103263651	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
02/12/2010	RF-Mesh	103280968	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
02/12/2010	RF-Mesh	103268377	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
02/12/2010	RF-Mesh	103373794	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
02/15/2010	RF-Mesh	102420744	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
02/17/2010	RF-Mesh	102460460	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
03/01/2010	RF-Mesh	103242328	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
03/01/2010	RF-Mesh	103258747	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
03/04/2010	RF-Mesh	101050791	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
03/05/2010	RF-Mesh	101100774	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
03/05/2010	RF-Mesh	101479105	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
03/17/2010	RF-Mesh	101233400	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
03/23/2010	RF-Mesh	103420744	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
03/26/2010	RF-Mesh	103207873	Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
03/29/2010	RF-Mesh	103279691	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
03/29/2010	RF-Mesh	103998215	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
03/29/2010	RF-Mesh	102450563	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
03/29/2010	RF-Mesh	103338029	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
04/08/2010	RF-Mesh	102457271	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16

**Annex A  
Oncor Advanced Meter Failures**

AMS Meter Failures for January 2009 Through September 2010							
Date Reported	Com Type	Serial Number	ProblemCategory	Meter Shop Cost	Loaded Cost	Field Adder	Cost Per Unit
04/27/2010	RF-Mesh	102604771	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
04/28/2010	RF-Mesh	102463957	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
05/06/2010	RF-Mesh	102994937	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
05/06/2010	RF-Mesh	103405503	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
05/06/2010	RF-Mesh	103407135	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
05/10/2010	RF-Mesh	102024161	Stopped Meter/No Rotation Annunciator	\$22.51	\$36.25	\$10.00	\$46.25
05/10/2010	RF-Mesh	101227321	Stopped Meter/No Rotation Annunciator	\$22.51	\$36.25	\$10.00	\$46.25
05/11/2010	RF-Mesh	101288372	Component Failure	\$30.01	\$48.33	\$10.00	\$58.33
05/12/2010	RF-Mesh	102467380	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
05/13/2010	RF-Mesh	101087282	Zigbee Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
05/27/2010	RF-Mesh	102457964	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
05/27/2010	RF-Mesh	104011397	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
05/28/2010	RF-Mesh	101269903	Zigbee Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
06/04/2010	RF-Mesh	101043364	Zigbee Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
06/04/2010	RF-Mesh	102594489	S/B Mode Failure	\$15.01	\$24.16	\$10.00	\$34.16
06/04/2010	RF-Mesh	102608354	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
06/04/2010	RF-Mesh	101040519	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
06/07/2010	RF-Mesh	102425216	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
06/09/2010	RF-Mesh	101244258	Component Failure	\$30.01	\$48.33	\$10.00	\$58.33
06/09/2010	RF-Mesh	101110053	Component Failure	\$30.01	\$48.33	\$10.00	\$58.33
06/15/2010	RF-Mesh	102613262	Error Codes	\$15.01	\$24.16	\$10.00	\$34.16
06/15/2010	RF-Mesh	102612802	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
06/17/2010	RF-Mesh	101252861	Component Failure	\$37.51	\$60.41	\$10.00	\$70.41
06/17/2010	RF-Mesh	102591579	Zigbee Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
06/17/2010	RF-Mesh	102611087	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
06/18/2010	RF-Mesh	101054591	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
06/25/2010	RF-Mesh	102618830	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
06/28/2010	RF-Mesh	102592706	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
07/08/2010	RF-Mesh	101257634	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
07/09/2010	RF-Mesh	104996814	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
07/09/2010	RF-Mesh	103272384	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
07/09/2010	RF-Mesh	102606074	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
07/12/2010	RF-Mesh	102593017	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
07/12/2010	RF-Mesh	102595649	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
07/12/2010	RF-Mesh	101111097	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
07/13/2010	RF-Mesh	101111890	Error Codes	\$15.01	\$24.16	\$10.00	\$34.16
07/13/2010	RF-Mesh	102605858	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
07/13/2010	RF-Mesh	102591502	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
07/13/2010	RF-Mesh	102605859	Error Codes	\$15.01	\$24.16	\$10.00	\$34.16
07/13/2010	RF-Mesh	102591496	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
07/14/2010	RF-Mesh	101100984	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
07/14/2010	RF-Mesh	101228979	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
07/14/2010	RF-Mesh	102471109	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
07/14/2010	RF-Mesh	102610607	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
07/14/2010	RF-Mesh	101106351	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
07/15/2010	RF-Mesh	102453401	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
07/15/2010	RF-Mesh	101076793	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
07/21/2010	RF-Mesh	103445189	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
07/22/2010	RF-Mesh	102465008	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
07/22/2010	RF-Mesh	102469530	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
07/23/2010	RF-Mesh	102608798	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101042031	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101259843	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101255135	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101286498	Non Revision D 2118 Event	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101067134	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16

**Annex A  
Oncor Advanced Meter Failures**

<b>AMS Meter Failures for January 2009 Through September 2010</b>							
<b>Date Reported</b>	<b>Com Type</b>	<b>Serial Number</b>	<b>ProblemCategory</b>	<b>Meter Shop Cost</b>	<b>Loaded Cost</b>	<b>Field Adder</b>	<b>Cost Per Unit</b>
07/28/2010	RF-Mesh	101287397	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101086424	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101271341	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101086970	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102000133	Non Revision D 2118 Event	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101247659	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101232924	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101250847	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101265968	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101251957	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103632462	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101288426	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101110564	Error Codes	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101059623	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101099175	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101250483	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101051925	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101059769	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101067632	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101077972	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101083275	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101084674	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101084870	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101085517	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101085861	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101094505	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101096206	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101096219	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101096424	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101099148	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101099297	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101099304	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101099520	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101099684	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101099857	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101100337	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101100360	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101100368	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101100374	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101101455	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101101478	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101102448	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101102791	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101106900	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101107001	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101111346	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101111421	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101111723	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101228706	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101229281	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101229306	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101230377	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101232684	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101236370	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101236600	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101237128	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16

**Annex A  
Oncor Advanced Meter Failures**

<b>AMS Meter Failures for January 2009 Through September 2010</b>							
<b>Date Reported</b>	<b>Com Type</b>	<b>Serial Number</b>	<b>ProblemCategory</b>	<b>Meter Shop Cost</b>	<b>Loaded Cost</b>	<b>Field Adder</b>	<b>Cost Per Unit</b>
07/28/2010	RF-Mesh	101237189	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101237818	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101237822	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101237900	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101238003	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101238602	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101238937	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101062050	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101071898	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101239002	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101075962	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101078047	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101239986	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101085029	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101243213	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101246188	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101085313	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101246383	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101085851	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101246846	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101086345	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101247366	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101265964	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101087348	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101265970	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101088600	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102612680	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101089832	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102613812	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102614810	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102615439	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102615908	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102616283	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102616852	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102618261	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102618761	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102618812	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102618983	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101053114	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101091992	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101093956	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101095202	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101096282	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101097112	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101098434	Display Stuck	\$0.00	\$0.00	\$10.00	\$10.00
07/28/2010	RF-Mesh	101101468	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101102086	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101102563	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101102803	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101105787	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101106345	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101108273	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101108626	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101110078	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101111003	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101112115	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16

**Annex A  
Oncor Advanced Meter Failures**

<b>AMS Meter Failures for January 2009 Through September 2010</b>							
<b>Date Reported</b>	<b>Com Type</b>	<b>Serial Number</b>	<b>ProblemCategory</b>	<b>Meter Shop Cost</b>	<b>Loaded Cost</b>	<b>Field Adder</b>	<b>Cost Per Unit</b>
07/28/2010	RF-Mesh	101230442	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101234351	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101236983	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101238193	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101238210	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101238239	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101238261	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101246184	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101247432	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101252338	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101265898	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101266739	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101296852	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101297187	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101297807	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101298150	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101298903	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101303057	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101303902	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101479093	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101481488	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101990082	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101990437	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101991667	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101993140	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101998490	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102426830	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102429405	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102429480	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102430184	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102432927	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102438175	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102456987	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102459188	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102463509	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102599120	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102614702	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102614712	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102614779	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101302816	Non Revision D 2118 Event	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101480834	Non Revision D 2118 Event	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101986173	Non Revision D 2118 Event	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101994989	Non Revision D 2118 Event	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102615108	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102615395	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102465375	Non Revision D 2118 Event	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102617734	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102618982	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102611298	Non Revision D 2118 Event	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103353173	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103634021	Non Revision D 2118 Event	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103466946	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103621094	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103621739	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103624155	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103627216	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16

**Annex A  
Oncor Advanced Meter Failures**

<b>AMS Meter Failures for January 2009 Through September 2010</b>							
<b>Date Reported</b>	<b>Com Type</b>	<b>Serial Number</b>	<b>ProblemCategory</b>	<b>Meter Shop Cost</b>	<b>Loaded Cost</b>	<b>Field Adder</b>	<b>Cost Per Unit</b>
07/28/2010	RF-Mesh	103636036	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103636081	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101093185	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103637641	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101093866	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101105576	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101275660	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101289281	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103637686	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101298769	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103642254	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101299791	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101304274	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	104027069	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101304344	Failed CT	\$0.00	\$0.00	\$10.00	\$10.00
07/28/2010	RF-Mesh	101473635	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101474495	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102446919	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101475129	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	104979893	Component Failure	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101040255	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101044134	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101049851	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101062330	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101230891	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101251700	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101255385	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101293030	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102602552	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102612894	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101273098	Non Revision D 2118 Event	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101296268	Non Revision D 2118 Event	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101480293	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101481980	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101985686	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101985966	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101988933	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101989142	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101990313	Non Volatile Memory	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101991043	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101991511	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101992462	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101992911	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101997133	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102008677	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102430691	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102434988	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102435541	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102438700	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102439340	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102441673	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102452832	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102457540	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102457692	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102470312	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102470979	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16

**Annex A  
Oncor Advanced Meter Failures**

<b>AMS Meter Failures for January 2009 Through September 2010</b>							
<b>Date Reported</b>	<b>Com Type</b>	<b>Serial Number</b>	<b>ProblemCategory</b>	<b>Meter Shop Cost</b>	<b>Loaded Cost</b>	<b>Field Adder</b>	<b>Cost Per Unit</b>
07/28/2010	RF-Mesh	102596891	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	102614168	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103623025	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103623402	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103623580	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103624360	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103624380	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103624391	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101230506	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	103627090	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101230868	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	103629885	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103631750	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103632146	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101234829	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	103633756	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101236388	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101237842	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	103634112	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103634726	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101238124	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	103636791	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101238715	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	103638015	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101240012	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	103640444	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101240307	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	103640879	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101241441	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	103640943	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101241460	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101242680	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	103641069	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101242924	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101245471	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	103642046	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101247235	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	103646565	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101247663	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	103647066	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101252467	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101252990	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	103647076	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101253873	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101253970	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	103649144	Failed CT	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101044821	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101255293	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101042706	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101047267	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101049457	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101049470	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101258243	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101259641	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101050123	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101264001	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00

**Annex A  
Oncor Advanced Meter Failures**

<b>AMS Meter Failures for January 2009 Through September 2010</b>							
<b>Date Reported</b>	<b>Com Type</b>	<b>Serial Number</b>	<b>ProblemCategory</b>	<b>Meter Shop Cost</b>	<b>Loaded Cost</b>	<b>Field Adder</b>	<b>Cost Per Unit</b>
07/28/2010	RF-Mesh	101052305	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101264252	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101052894	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101264863	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101265174	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101055969	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101059995	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101265180	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101060389	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101265974	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101267548	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101061249	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101466723	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	102613394	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101062969	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	102617250	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101047224	Revision D Non Communication	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101073070	Revision D Non Communication	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101065356	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101228289	Revision D Non Communication	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101228755	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101069491	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101074541	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101228823	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101075320	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101075630	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101241765	Revision D Non Communication	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101081636	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101252012	Revision D Non Communication	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101081746	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101253052	Revision D Non Communication	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101083664	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101253230	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101085965	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	102612237	Revision D Non Communication	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101086891	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	102613207	Revision D Non Communication	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101095941	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101086967	Unprogrammed	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101103088	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101105693	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101106157	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101106648	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101101475	Unprogrammed	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	101111600	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	101228192	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
07/28/2010	RF-Mesh	102614563	Unprogrammed	\$15.01	\$24.16	\$10.00	\$34.16
07/28/2010	RF-Mesh	103991721	Unprogrammed	\$15.01	\$24.16	\$10.00	\$34.16
07/29/2010	RF-Mesh	104136723	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
07/29/2010	RF-Mesh	104154322	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
07/29/2010	RF-Mesh	102459588	Erratic Register Reading	\$15.01	\$24.16	\$10.00	\$34.16
08/02/2010	RF-Mesh	104116922	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
08/02/2010	RF-Mesh	103279433	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
08/02/2010	RF-Mesh	104132964	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
08/03/2010	RF-Mesh	103618211	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
08/09/2010	RF-Mesh	105081316	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16

**Annex A  
Oncor Advanced Meter Failures**

<b>AMS Meter Failures for January 2009 Through September 2010</b>							
<b>Date Reported</b>	<b>Com Type</b>	<b>Serial Number</b>	<b>ProblemCategory</b>	<b>Meter Shop Cost</b>	<b>Loaded Cost</b>	<b>Field Adder</b>	<b>Cost Per Unit</b>
08/10/2010	RF-Mesh	105077423	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
08/11/2010	RF-Mesh	104998221	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
08/11/2010	RF-Mesh	105098451	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
08/16/2010	RF-Mesh	105096470	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
08/18/2010	RF-Mesh	104021173	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
08/18/2010	RF-Mesh	104980760	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
08/19/2010	RF-Mesh	105061325	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
08/19/2010	RF-Mesh	103610310	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
08/24/2010	RF-Mesh	103342974	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
08/25/2010	RF-Mesh	105067410	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
08/31/2010	RF-Mesh	103208329	Complaint Test	\$15.01	\$24.16	\$10.00	\$34.16
08/31/2010	RF-Mesh	103510121	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
09/01/2010	RF-Mesh	103436563	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
09/02/2010	RF-Mesh	101279375	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
09/03/2010	RF-Mesh	101298422	Service Disconnect Malfunction	\$15.01	\$24.16	\$10.00	\$34.16
09/07/2010	RF-Mesh	102423902	Error Codes	\$15.01	\$24.16	\$10.00	\$34.16
09/08/2010	RF-Mesh	105199442	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
09/08/2010	RF-Mesh	102427106	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
09/09/2010	RF-Mesh	105135956	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
09/10/2010	RF-Mesh	104179527	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
09/10/2010	RF-Mesh	105009839	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
09/10/2010	RF-Mesh	105050964	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
09/10/2010	RF-Mesh	105067172	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
09/10/2010	RF-Mesh	104123743	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
09/10/2010	RF-Mesh	104158089	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
09/13/2010	RF-Mesh	103621151	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
09/13/2010	RF-Mesh	102601694	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
09/13/2010	RF-Mesh	102603620	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
09/14/2010	RF-Mesh	102610806	Revision D 2118 Event	\$0.00	\$0.00	\$0.00	\$0.00
09/14/2010	RF-Mesh	105133717	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
09/15/2010	RF-Mesh	103626692	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
09/15/2010	RF-Mesh	105099595	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
09/15/2010	RF-Mesh	103642798	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
09/15/2010	RF-Mesh	105098033	Blank/Partial Display	\$15.01	\$24.16	\$10.00	\$34.16
09/15/2010	RF-Mesh	101085427	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
09/15/2010	RF-Mesh	103284346	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
09/15/2010	RF-Mesh	102611574	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
09/15/2010	RF-Mesh	102441366	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
09/20/2010	RF-Mesh	105427232	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
09/28/2010	RF-Mesh	104183131	LAN Radio Not Communicating	\$15.01	\$24.16	\$10.00	\$34.16
09/28/2010	RF-Mesh	104101391	Display Stuck	\$15.01	\$24.16	\$10.00	\$34.16
09/29/2010	RF-Mesh	105429712	Component Failure	\$22.51	\$36.25	\$10.00	\$46.25
				\$10,893.63	\$17,543.10	\$6,950.00	\$24,493.10